

Figure 1. The Moose Dool Project is located in the headwaters of the Little North Fork Coeur d'Alene River watershed.



Figure 2. Example water quality and fisheries habitat problems treated by Moose Dool Watershed Restoration Project.



Figure 3. Contractors at work excavating a stream crossing during road decommissioning.



Before



After

Figure 4. A road located adjacent to a stream and in its floodplain before and after restoration activities.






Figure 5. The Moose Drool project area roads before and after the project.



Figure 6. The North Idaho Fly Casters Conservation Festival with the Forest Service and contractors and volunteers in June 2015.







Figure 7. Tour of Moose Drool Project with Watershed Advisory Group, at a site showing road decommissioning and large wood placement instream.